



## 5035 & DRY WEIGHT STATE SAMPLING REQUIREMENTS

STATE	STATE REQUIREMENTS		
	Dry Weight	% Moisture	5035
Alabama	NR	NR	Accepts
Alaska-UST	Y	Y	Accepts, has guidance
Arizona	Y	NR	Accepts, has guidance
Arkansas	Y	Y	NR
California*	NR	NR	Y, has guidance
Colorado	Y	Y	NR
Connecticut	Y	NR	Y, has guidance
Delaware	Prefers	Y	Accepts
Florida*	Y	Y	Y, has guidance
Georgia	NR	NR	Y, has guidance
Hawaii	Y	NR	Y, has guidance
Idaho	NR	NR	NR
Illinois*	Y	NR	Y, has guidance
Indiana	Y	NR	Y
Iowa-UST	NR	NR	Accepts
Kansas*	NR	NR	Accepts
Kentucky-UST	NR	NR	NR
Louisiana*	Y (RECAP) ?	NR	Y, has guidance
Maine	NR	NR	Accepts
Maine-UST	NR	NR	NR
Maryland	NR	NR	Accepts
Massachusetts	Y	NR	Y, has guidance
Michigan	Y	Y	Y, has guidance
Minnesota	Y	Y	Y, has guidance
Mississippi	Y	NR	Y
Missouri	NR	NR	Y, has guidance
Montana-UST	Y	Y	Accepts
Navy NAVSEA program			
Nebraska	Y	NR	NR
Nevada	NR	NR	Accepts
New Hampshire*	Y	NR	Y, has guidance
New Jersey	Y	Y	Y, has guidance
New Mexico	NR	Y	NR
New York*	Y	Y	NR
North Carolina	Y	NR	Y, has guidance



STATE	STATE REQUIREMENTS		
	Dry Weight	% Moisture	5035
North Dakota	NR	NR	Accepts
Ohio	NR	NR	NR
Ohio-VAP	NR	NR	Y, has guidance
Oklahoma	NR	NR	NR
Oregon*	NR	NR	NR
Pennsylvania*	Y	NR	Y
Rhode Island	Y	NR	Y
South Carolina	Y	Y	Y, has guidance
South Dakota	NR	NR	NR
Tennessee	NR	NR	Accepts
Texas*	Y (TRRP)	NR	Accepts, has guidance
Utah*	NR	NR	NR
Utah-UST	NR	NR	NR
Vermont	NR	NR	NR
Virginia	NR	NR	Y
Washington	Y	NR	Y, has guidance
West Virginia	Y	NR	Y
Wisconsin	Y	NR	Has guidance, No Encores
Wyoming-UST	NR	NR	NR

Y = Requires                      NR = Not Required                      \* = NELAP